UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,834,617 B1

DATED

: December 28, 2004

INVENTOR(S) : Hsieh et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1,

Line 24, "structure is also complicate" should read -- structure is also complicated --

Column 2,

Line 22, "FIG. 6 taken along line VII-VII; and" should not be indented Lines 47-48, "housing part of accessory for" should read -- housing part of the accessory for --

Column 3,

Line 22, "rough 19 for cleaning," should read -- trough 19 for cleaning, --Line 36, "The lamp is provided a florescent tube" should read -- The lamp provided is a florescent tube --

Column 4,

Line 54, "opposite left an right" should read -- opposite left and right --

Column 6,

Line 13, "is continuous or discontinuous groove extending and tuning in substantially" should read -- is a continuous or discontinous groove extending and turning in substantially --

Signed and Sealed this

Page 1 of 1

Twelfth Day of July, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office